

Macintosh: Bad F-line Instruction Error (11/95)

Revised: 11/20/95 Security: Everyone

Macintosh: "Bad F-line Instruction" Error (11/95)

Article Created: 13 August 1991 Article Last Reviewed: 20 November 1995

TOPIC -----

I am getting a "Bad F-line Instruction" errors on my 68k Macintosh computer. What causes these errors?

DISCUSSION -----

In System 7.x, the "Bad F-line Instruction" error is also referred to as the "Co-processor Not Installed" or "No FPU Installed" error; in System 6.0.7 it is referred to as the ID=10 error.

F-Line instructions are used to access attached processors, such as a floating-point math co-processor. A bad F-Line instruction is a bad Floating Point Unit (FPU) call. However, when you see this on computers without FPUs, or in applications that do not support an FPU, then it is probably a spurious error. These messages often indicate software related errors generated by a program that has extraneous program code. On very rare occasions a hardware failure generates these errors.

With System 6.0.7, these errors do not have a direct relationship with floating point co-processors; you will not resolve this error by installing an FPU. In System 7.x, there may be a problem with the math chip, or it may be an unrelated software error.

The error may be caused by bad code in the application which is calling a processor that is not present or calling a memory location that is not there. There may be a corrupted application or an extension causing some spurious memory problem.

A possible solution is to remove and reinstall the application and/or remove and reinstall the system software.

NOTE: On Power Macintosh computers, there may be additional causes to these

..TIL08709-Macintosh-Bad_F-line_Instruction_Error_11-95_(TA47101).pdf

types of errors. See the Tech Info articles, "Power Macintosh Computers: No FPU Installed Error" and "Power Macintosh: Type 11 & No FPU Errors Technote" for additional information.

Article Change History: 20 Nov 1995 - Added additional technical information. 21 Feb 1995 - Added keyword; made minor technical updates. 21 Sep 1994 - Reviewed.

Support Information Services

Copyright 1991-95, Apple Computer, Inc.

Tech Info Library Article Number:8709