

PowerBook 200 Series: Type III Battery and System 7.5.1 (9/95)

Revised: 9/26/95 Security: Everyone

PowerBook 200 Series: Type III Battery and System 7.5.1 (9/95)

Article Created: 22 June 1995 Article Reviewed/Updated: 26 September 1995

TOPIC -----

I have a Macintosh PowerBook Duo (200 series). Since I installed the System 7.5 Update 1.0, the external recharger gives a red light when I try to charge a Type III battery. This occurs even after following the instructions for loading the proper power management code into the charger. This happened with a brand new battery.

DISCUSSION -----

Resolution

You need to install the Type III battery extension into the System folder. Do not remove this extension even after you have installed System 7.5 and the System 7.5 Update 1.0. The extension is on a disk called Battery Tools, which ships with the Type III battery.

Background

When the System 7.5 Update 1.0 extension loads, it replaces the PG&E (battery management) code. This PG&E code then reloads to the external battery charger. Because of this, the external recharger does not recognize the Type III batteries and you get the red light. However, the batteries charge fine in the computer itself.

Conclusion

You need to use the Type III Battery extension to get the external charger to work with System Software 7.5.1 (System 7.5 plus the System 7.5 Update 1.0) and Type III batteries.

..TIL18149-PowerBook_200_Series-Type_III_Battery_and_System_7-5-1_9-95_(TA34052).pdf

These articles can help you locate the software (Type III Battery extension) mentioned here:

- Where To Find Apple Software Updates Lists online services for "free" Apple software updates.
- Obtaining Apple Product Support in the USA Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library.

This article was published in the "Information Alley": Volume II, Issue 9, Page 19

Article Change History: 26 Sep 1995 - Added Info Alley information; updated article.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:18149