

PowerBook: Sys 7.5 Update 2.0 Changes (5/96)

Revised: Security:	5/17/96 Everyone		
PowerBook: Sys	7.5 Update 2.0 Ch	anges (5/96)	
Article Created	d: 17 May 1996		
TOPIC			
Software Update component that	e to System 7.5.3,	by installing Syst een listed, along w	m PowerBook 5300 System em 7.5 Update 2.0. Each ith a description of what the
DISCUSSION			
Item		rBook 5300 Software Update	System 7.5 Update 2.0
====	=====		
APPLE MENU ITEN			
CHOOSER Support for Ope	en Transport.	7.5	7.5.4
FIND FILE Numerous fixes		1.1.1	1.1.2
CONTROL PANELS			
order if the so	n with internation cript system and t		1.1.2 ems would end up out of different ideas about
	nange so that inte		3.0.3 find it easier to build a ot be seen by end users.

7.5.5 7.5.7 GENERAL CONTROLS Changed the default setting of the Improper Shutdown dialog to ON. This changed from 7.5.5 to 7.5.6, and then back again with 7.5.7. 2.7 LAUNCHER 2.8 Allow for the selection of an initial default category by name instead of by number. Also changed the default button spacing for the three button sizes so that 9x3 small buttons, 6x2 medium buttons and 4x1 large buttons have exactly the same window size. 7.5.4 7.5.5 MONITORS This version works on all Macintoshes (except the Plus and Classic). The changes were to make Monitors work with Display Manager 2.0 on pre-7.5.2 CPUs, by merging the 7.5.2 versions with the 7.5 version. MOUSE 7.5.2 7.5.3 Added back Mouse Tracks and Thick I-Beam cursor to PowerBooks which support them. Mouse 7.5.2 had removed them for all PowerBooks. NETWORK 3.0.2 3.0.3 Open Transport support. (The network control panel was made OT aware so it will not run if OT is active.) NETWORK SOFTWARE SELECTOR This utility allows a user of 68030-, 68040-, and early PowerPC-based computers to choose between Open Transport and classic AppleTalk networking if both are installed. (You must restart the computer for the change to take effect.) PCI-based computers support only Open Transport. SPEECH N/A 1.4.1 Allows you to change the default voice and other Speech Manager related settings. TRACKPAD 7.5.4 7.5.5 Fixes a problem where the mouse and trackpad settings would lose sync over restart on PowerBook 500 series machines. CONTROL STRIP MODULES _____ 1.0 MONITOR BITDEPTH N/A Part of the Control Strip package. It allows the user to easily change the bit depth of a monitor. MONITOR RESOLUTION N/A 1.0.1 Support for Display Manager 2.0 on pre-7.5.2 CPUs. (Similar to the Monitors changes.)

EXTENSIONS

EM EXTENSION	3.0.2	3.0.3
Same as Extensions Manger Control	Panel 3.0.3.	
ABOUT APPLE GUIDE	1.2	1.3
Some wording was changed.		
ABOUT COLOR SW PRO CMM	1.0	1.0.1
Some wording was changed.		

APPLE GUIDE 1.2.7 2.0.2
Fixed script system handling by first attempting to use the script code from the current database. This enables better handling of localized database files and fixes a Look For problem in Japan systems.

• Fixed a memory leak (~2k) of an international resource that occurred everytime a database was opened. This occurred in Apple Guide's heap.

• Fixed a bug in <Delete Index> that affected Japanese systems.

• Fixed problems with mixed mode handling of installed coach and context handlers. This occurred on PowerMacs running native Apple Guide 1.2.5 and installing handlers from native or 68K applications.

• Fixed an index bug that originally surfaced on Japanese systems. When multiple mixin files (aka additions) were in use, items would disappear from the index list. The real culprit here was a bug that was dropping every 21st index item from the combined index list from all the mixins in use. This bug would occur on any system software version, not just Japanese.

• Fixed improper handling of international resources that could crash some systems.

• Fixed a problem where mixin files whose gestalt criteria failed on PowerMacs causing Apple Guide to shut down completely. For example, if you are on a PowerMac and a PowerBook mixin was present on the machine, v1.2.5 would completely shut down because that mixin couldn't be used. It now just ignores that mixin and continues running.

• Now built with a 'weak' link to QuickTime. This means that when run on a PowerMac, Apple Guide will continue to run even if QuickTime isn't installed. Previously, 1.2.5 would refuse to start up if QuickTime wasn't present on the machine.

- Added Gestalt selector 'ag_v' to return the current installed version of Apple Guide. Very similar to the 'sysv' result code.

• Added localizable error strings used in various abort msgs.

• Modified index sorting code to default to USACII sorting only if the current script is Roman and the current language is English. Previously, 1.2.5 would default to USASCII on any Roman script system.

• Fixes an incompatibility with Microsoft Office Manager introduced by Apple Guide version 2.0. • Fixes a problem which could cause Apple Guide to crash at undetermined points. APPLE MODEM TOOL 1.5 1.5.5 Supports higher speed serial connections (up to 230kb) due to the new SerialDMA driver which is supported on the Macintosh 680x0 AV and Power Macintosh desktop machines. 3.6.1 3.6.1RevB APPLESHARE Set the bundle bit. This fixes a problem where the icon of the AppleShare file might not be displayed correctly. FINDER HELP 7.5.3 7.5.5 Just keeping in sync with the Finder. FINDER SCRIPTING EXTENSION 7.5.5 7.5.3 Just keeping in sync with the Finder. IRTALK 1.2 1.3.1 IRTalk 1.3.1 provides support for Open Transport. A machine that is using IRTalk and has OT installed and turned on, must have IRTalk 1.3 or greater, or a crash will occur. LASERWRITER 8 8.3.2 8.3.3 A change was made to keep third party applications that fail to call PROpen from crashing when printing. MACINTOSH GUIDE 1.2 1.3 A large number of changes and additions were made to the Guide information. NETWORK EXTENSION 7.1.3 7.5.5 Keeping in sync with the Finder. Some BlockMove calls were changed to BlockMoveData for speed. PB 5300 GUIDE ADDITIONS 1.0 1.3 A large number of changes and additions were made to the Guide information. PRINTER DESCRIPTIONS _____ LASERWRITER 16/600 PS-J N/A 1.1 Slight changes to printer information for driver usage. LASERWRITER 4/600 PS N/A 1.0 Postscript parameters and printer information for the LW 4/600 PS printer. LASERWRITER COLOR 12/600 PS N/A 1.1.1 Slight changes to printer information for driver usage. PRINTER SHARE 1.1.2 1.1.3

Increased the stack space internally to work with Open Transport. Printer Share 1.1.3 is required to work with Open Transport.

SHORTCUTS 1.2 1.3 A number of small changes were made to ShortCuts, including a few wording changes, as well as some additional tips.

SPEECH MANAGER 1.3 1.4 Previous to version 1.4 of the PlainTalk family of software, all of Apple's text-to-speech software and speech recognition was packaged together in one big installer (and there was no Spanish text-to-speech before version 1.4). As of version 1.4, there are three separate installers: "English Text-to-Speech", "Mexican Spanish Text-to-Speech", and "English Speech Recognition". The text-to-speech installers both install the Speech Manager extension.

VOICES $$\rm N/A$$ Different sounding voices for use with Speech 1.4 (MacinTalk 2 or 3 depending on the CPU).

SYSTEM FOLDER

FINDER 7.5.4 7.5.5 Fixes a crash that would occur when you drag one Zip disk onto another.

SYSTEM 7.5.2 UPDATEN/A7.5.3This replaces the PowerBook 5300/190/2300 Enabler.It includes thefollowing additional bug fixes:

• Fixed a problem with the BatteryPrediction code which could cause a PowerBook to crash when the machine is booted.

• Fixed a problem where At Ease would hang when command-power was depressed without a debugger present.

• Fixed a problem in PowerMgrLib that could cause a crash when turning AppleTalk off, then back on, then opening the Chooser.

• Includes the 2300c track pad update.

• Includes the 7.5.2 Printing Fix.

• Changed a constant (kMaxDepth) from 8 to 16 in MouseTracks.c (part of QuickDraw). This is a test to see whether or not mouse tracks can be turned on based on the screen depth and it was too shallow.

• Fixed a problem where PC cards were left unlocked after waking from sleep, which could lead to possible data loss.

• Fixed a problem with notification manager alerts on all machines. Before the fix, the alerts that involve a flashing icon, could result in the wrong icon being used in the Application Menu after the alert is dismissed. Another of the problems this fixes is that the clock (all machines) and battery level indicator

(PowerBooks/Duos) would be erased, stay blank briefly, and be redrawn when an alert sound is played.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19813