



Tech Info Library

Pinpoint 1.0, 1.1: RamWorks/Print Buffer

Revised: 1/20/86
Security: Everyone

Pinpoint 1.0, 1.1: RamWorks/Print Buffer

=====

Symptom:

There is a problem setting the Print Buffer on using the Applied Engineering Super Desktop Expander version 4.5. Once you access a desktop accessory, you can no longer print. For that matter, your machine will hang when attempting printing.

Solution:

Re-Install Desktop Expander without the print buffer option.

Until we work this out with Applied Engineering, the user should disable the print buffer option. This means that they should start again from their original AppleWorks, install AE patches, then Pinpoint.

NOTE: Apple Computer Inc. is not responsible for the contents of this article.

Pinpoint Publishing

Tech Info Library Article Number:1669