



Tech Info Library

ImageWriter II Ribbon Advance Problems

Revised: 1/17/92
Security: Everyone

ImageWriter II Ribbon Advance Problems

=====
This article last reviewed: 29 March 1988

BEFORE YOU START: Familiarize yourself with the ImageWriter II Technical Procedures. Be sure to follow proper ESD procedures.

PROBLEM DESCRIPTION: A customer might complain that the print will become light then dark again, or that the ribbon wears through in certain spots. A technician might notice that the ribbon drive gear will turn counter-clockwise when the carriage assembly is moved - but only when the carriage assembly is moved in one direction.

CAUSE: The ribbon frame assembly might be defective.

CURE: Replace the ribbon frame assembly.

Note: Refer to General Troubleshooting Procedures if replacing the ribbon frame assembly did not cure the problem.

Copyright 1988, Apple Computer, Inc.

Tech Info Library Article Number:2077