

Tech Info Library

Apple IIc Power-On Light Flashes

Revised: 7/17/92 Security: Everyone

Apple IIc Power-On Light Flashes

Article Created: 29 March 1988

Article Last Reviewed: 15 April 1992 Article Last Updated: 15 April 1992

PROBLEM DESCRIPTION: The Apple IIc power-on light flashes after

installing a new logic board.

CAUSE: The internal power supply or keyboard might need to be replaced.

CURE: This can be caused by low voltage conditions. Confirm the failure by trying another circuit or AC Power Pack before proceeding. Then replace the keyboard. If the keyboard does not solve the problem replace the internal power supply.

Note: Refer to the Apple IIc General Troubleshooting Procedures if replacing the keyboard or power supply does not solve the problem.

Copyright 1988, 1992 Apple Computer, Inc.

Tech Info Library Article Number: 2079