



Tech Info Library

Hayes InterBridge version 1.06: Improvements

Revised: 1/13/88
Security: Everyone

Hayes InterBridge version 1.06: Improvements

=====

This article last reviewed: 13 August 1987

Version 1.06 of Hayes InterBridge corrects several problems that were reported in version 1.05:

- Down bridge: causes the bridge to become inactive or inaccessible, a large number of buffer allocation errors, or cause the bridge to stop functioning completely.
- Missing bridge: could occur in AppleTalk networks connected with four or more InterBridges. Causes the network manager software to be unable to see the bridge.
- Packet errors: when an InterBridge is combined on an AppleTalk network with a Kinetics Fastpath device, a large number of packet errors occur.

Tech Info Library Article Number:2310