



# Tech Info Library

## LaserWriter IINT/NTX: COM1: Port Error in Owner's Manual

Revised: 3/4/90  
Security: Everyone

LaserWriter IINT/NTX: "COM1:" Port Error in Owner's Manual

=====

This article last reviewed: 21 July 1989

TOPIC -----

There is an error in the LaserWriter IINT/NTX Manual (Apple part #030-3215-A) concerning the data bits for word length.

DISCUSSION -----

The LaserWriter IINT/NTX Manual, in the section that tells how to use the LaserWriter II with MS-DOS applications (page 113) says to use the DOS MODE command to set the COM1: port to 7-bit word length. On page 120, the manual states that the default serial word length is 7 data bits.

These are errors. The COM1: port word length must be set to 8 bits, and the default serial word length is also 8 bits.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:4044