



# Tech Info Library

## Macintosh IIsi: Troubleshooting NuBus Card Installation Problems

Revised: 7/20/92  
Security: Everyone

Macintosh IIsi: Troubleshooting NuBus Card Installation Problems

=====  
Article Created: 20 December 1991  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

### TOPIC -----

I am having a problem installing TokenTalk and EtherTalk NB cards on our Macintosh IIsi computers. We have not been able to get any of the systems up on the network.

### DISCUSSION -----

Without more detailed information about the problems you are experiencing, we can offer only some troubleshooting measures:

- Ensure that the network is properly terminated.
- If you are running System 6.0.7, ensure that the Network Product Installer is used to installed the Network CDEV and TokenTalk/EtherTalk drivers.
- If you have the Macintosh IIsi NuBus Adapter Card installed and the EtherTalk NB Card is properly installed, ensure that the jumper on the EtherTalk NB Card is set for BNC.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:9571