



# Tech Info Library

## PowerBook 100, 140, and 170: Fix Dates of Three Components

Revised: 5/17/94  
Security: Everyone

PowerBook 100, 140, and 170: Fix Dates of Three Components

=====  
Article Created: 27 October 1992

TOPIC -----

How can I tell if my PowerBook has all of the known fixes installed already?

DISCUSSION -----

Below is a list of the manufacturing cut-in dates for the Inverter Shield, Display Cable Shim, and Revision B Floppy Disk Drive:

Inverter Shield:

F2150XXX 140's built in Fremont  
CK205XXX 170's built in Cork

Display Shim:

F2208XXX 140's built in Fremont  
FCXXXXXXX 140's built in Fountain  
CK212XXX 140's built in Cork

Rev B Floppy Drive:

F2211XXX 140's 4/40 built in Fremont  
F2212XXX 140's 4/80 built in Fremont  
FC213XXX 140's built in Fountain  
CK213XXX 140's built in Cork  
CK213XXX 170's built in Cork

Notes:

- 1) If a PowerBook has been sent back to the Central Product Repair Center for repair, it may have one or all of these fixes already installed.
- 2) All PowerBook 100 external floppy drives were built before the Revision B floppy drive was available, so all external floppy drives are Revision A mechanisms unless they have been returned to the Central Product Repair Center or a dealer for repair.

3) The Display Cable Shim and the Inverter Shield haven't been identified as necessary on the PowerBook 100.

Support Information Services

Copyright 1992, Apple Computer, Inc.

Tech Info Library Article Number:10569