



Tech Info Library

Macintosh TV & Sound Manger 3.0 Problem (12/94)

Revised: 12/2/94
Security: Everyone

Macintosh TV & Sound Manger 3.0 Problem (12/94)

=====
Article Created: 18 May 1994
Article Reviewed/Updated: 2 December 1994

TOPIC -----

The "Sound 8.0.1" control panel and the "Sound Manager 3.0" extension do not seem to work correctly on my Macintosh TV. After I installed these two files (replacing pre-installed Sound 7.1), monaural sounds came from the right channel ONLY through headphones and the Macintosh TV computer's internal stereo speakers, whereas with Sound 7.1 mono sounds were in both left and right channels. Audio CDs and stereo TV broadcasts were fine, however. When I removed Sound 8.0.1 and Sound Manager 3.0 and restored Sound 7.1, everything was fine. Installing Sound Manager 3.0 by itself produced the same result. This is a problem, because many new CD-ROMs now require Sound Manager 3.0. Is a fix-it 'patch' going to be made available?

DISCUSSION -----

This problem has been corrected in System 7.5. The new Sound Manager extension functionality has been built into the System.

Article Change History:
02 Dec 1994 - Updated article to reflect System 7.5.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:15386