



# Tech Info Library

## Power Macintosh: PATHWORKS LAT Problem (7/94)

Revised: 7/13/94  
Security: Everyone

Power Macintosh: PATHWORKS LAT Problem (7/94)

=====  
Article Created: 12 July 1994

TOPIC -----

The PATHWORKS LAT connection tool intermittently disconnects when running on any model of Power Macintosh.

DISCUSSION -----

This problem is being worked on by both Apple Computer and Digital Equipment Corporation (DEC) engineers. The problem has not yet been identified so there is no estimated date for a fix. The disconnect only seems to happen when there are high collisions on the Ethernet where a Power Macintosh is connected.

Until a fix is available, the work around is to use the AppleTalk-LAT Gateway. The Gateway must be configured on a 680x0 processor based Macintosh. See the PATHWORKS installation manual for installation and set-up details.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:15810