



Tech Info Library

Power Macintosh 9500: Worldscript Updater 1.0 Issue (8/95)

Revised: 8/31/95
Security: Everyone

Power Macintosh 9500: Worldscript Updater 1.0 Issue (8/95)

=====
Article Created: 14 July 1995
Article Reviewed/Updated: 31 August 1995

TOPIC -----

I installed Chinese Language Kit (CLK) 1.1 and Chinese Language Kit Updater 1.1.1 on my Power Macintosh 9500/120 computer. Why doesn't it work?

DISCUSSION -----

WorldScript Updater 1.0 must be installed first for the Chinese Language Kit to work on the Power Macintosh 7200/7500/8500/9500 series of computers.

Installation Steps

You must perform the installation in the following order:

Step 1

Install WorldScript Updater 1.0

Step 2

Install Chinese Language Kit 1.1

Step 3

Install Chinese Language Kit Updater 1.1.1

If you install WorldScript Update 1.0 last, your System file could end up being corrupted. If this occurs, you need to perform a "clean install" of the System Software, then reinstall the preceding items in that order.

Additional Information

Refer to the Tech Info Library article titled "System 7.5: Clean Install Procedure" for clean install instructions or the article titled System 7.5 Clean Install in the "Information Alley" Volume I, Issue 18, Page 8.

This article was published in the "Information Alley":
Volume II. Issue 8, Page 11

Article Change History:

31 Aug 1995 - Added other PCI-based Macintosh information.

28 Aug 1995 - Updated from Info Alley.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:18165