



Tech Info Library

Power Macintosh 7500 & 8500: Mac ODBC 2.1 Install Issue (10/95)

Revised: 10/2/95
Security: Everyone

Power Macintosh 7500 & 8500: Mac ODBC 2.1 Install Issue (10/95)

=====
Article Created: 2 October 1995

TOPIC -----

I have a Power Macintosh 7500 and 8500. I easily installed Mac ODBC version 2.1 from the Mac ODBC Developer's Kit and now I get an Error Type 10 during startup. What's wrong?

DISCUSSION -----

When you install the 680x0 processor-based version of Mac ODBC 2.1 on a Power Macintosh 7200, 7500, 8500, or 9500, an older version (1.1.2) of the Shared Library Manager is installed. Unfortunately, the install process deletes the newer Shared Library Manager 2.0 that is already present on these computers with Open Transport version 1.0.x. Power Macintosh 7200, 7500, 8500, or 9500 computers should be pre-installed with Shared Library Manager 2.0 and Shared Library Manager PPC 2.0 with System Software 7.5.2.

You can correct this by removing the old Shared Library Manager and reinstalling the newer version from the Power Macintosh 7500 or 8500 CD. This can be done by custom installing the Networking Software.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:18683