



Tech Info Library

Macintosh IIvx: Replacing Logic Board, Buzzing Sound (3/96)

Revised: 3/28/96
Security: Everyone

Macintosh IIvx: Replacing Logic Board, Buzzing Sound (3/96)

=====

Article Created: 28 March 1996

TOPIC -----

After installing a new logic board in a Macintosh IIvx, the computer no longer makes the usual startup chime, it buzzes for three seconds. Then with power staying on, no video is displayed. What is wrong?

DISCUSSION -----

You need to install VRAM on the logic board. Once this is done the computer should startup in a normal fashion.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19523