Tech Info Library

Kensington Turbo Mouse: Using with System 6.0.5 Requires Patch

```
Revised:        8/8/91
Security:       Everyone
```

Kensington Turbo Mouse: Using with System 6.0.5 Requires Patch

===

Article Created: 18 April 1991
Article Last Reviewed:
Article Last Updated:

TOPIC ---

My Macintosh IIx (running System 6.0.5.) freezes when the system is
starting up. The problem is intermittent and happens only when the
mouse--a Turbo Mouse from Kensington--is plugged in. (We have swapped out
the mouse and the keyboard.)

DISCUSSION ---

The Turbo mouse has a problem with System 6.0.5. Kensington has a patch for
this. For contact information, search the Tech Info Library under
"Kensington".

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:7517