Tech Info Library

LaserWriter II: 6MB Configuration Won't Cause Problems (11/94)

```
Revised:        11/10/94
Security:       Everyone
```

LaserWriter II: 6MB Configuration Won't Cause Problems (11/94)

===

Article Created: 13 August 1991
Article Reviewed/Updated: 10 November 1994

TOPIC ---

I've been told that a 6MB RAM configuration in a LaserWriter IIntx can cause
problems.

The only documentation I've been able to locate states that the 6MB
configuration can be physically installed, but that the printer will recognize
only 5MB.

Will leaving excess memory in the otherwise empty slots cause any damage or
problems with the printer or the attached systems?

DISCUSSION --

As you have discovered, 1MB of the 6MB is not be recognized. We are not aware
of any problems that could be caused by having 6MB installed in the printer.

Article Change History:
10 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94 Apple Computer, Inc.

Tech Info Library Article Number:8716