Tech Info Library

Apple IIc Serial Loopback Cable: Pinouts (10/94)

```
Revised:        10/18/94
Security:       Everyone


Apple IIc Serial Loopback Cable: Pinouts (10/94)


=====================================================================

Article Created: 27 July 1985
Article Reviewed/Updated: 18 October 1994


TOPIC -------------------------------------------------------------

This article describes the pinouts for the IIc serial loopback cable.

DISCUSSION --------------------------------------------------------

Below are the pin configurations for the Apple IIc serial loopback cable:

     Modem           Printer
      port            port


         1    to    5
         5    to    1
         2    to    4
         4    to    2


Ground the connector shields together.



Article Change History:
18 Oct 1994 - Reviewed for technical accuracy, revised formatting.


Support Information Services


Copyright 1988-94 Apple Computer, Inc.


Tech Info Library Article Number:1218
```