Tech Info Library

Monitor II Displays Raster Line

```
Revised:        1/17/92
Security:       Everyone
```

Monitor II Displays Raster Line

===

This article last reviewed: 29 March 1988

PROBLEM DESCRIPTION: The Monitor II displays a single line
across the screen. There is no other display.

CAUSE: Yoke wires might not be connected properly.

CURE: Check the connections for the green/white pair of yoke
wires and make sure they are properly connected to the main
electronics assembly. At present they are connected to location
V-DY (center of main electronics assembly).

Copyright 1988, Apple Computer, Inc.

Tech Info Library Article Number:2069