# Tech Info Library

## LaserWriter: Possible Causes of Curved/Skewed Straight Lines

```
Revised:        3/11/88
Security:       Everyone
```

LaserWriter: Possible Causes of Curved/Skewed "Straight" Lines

======================================================================

This article last reviewed: 15 February 1988

If a line drawn as a straight vertical lines on the Macintosh's screen is
not a perfectly vertical line when printed on a LaserWriter, it may be due
to:
- the type of paper stock being used
- a problem with the paper feed assembly
- a faulty laser scanner unit

If the line is straight but not perfectly vertical when printed, it may
be due to the skew adjustment.

Tech Info Library Article Number:2644