Tech Info Library

MS BASIC Interpreter 2.1: Problem With Macintosh Plus Sound

```
Revised:        3/22/88
Security:       Everyone
```

MS BASIC Interpreter 2.1: Problem With Macintosh Plus Sound

==

This article last reviewed: 15 February 1988

The Microsoft BASIC Interpreter version 2.1 has problems with the Macintosh
Plus sound routines. The solution is to upgrade to the Microsoft BASIC
Interpreter version 3.0.

Tech Info Library Article Number:2657