Tech Info Library

Apple EtherTalk Card: Revisions J and K Explained

```
Revised:        10/4/89
Security:       Everyone
```

Apple EtherTalk Card: Revisions "J" and "K" Explained

==

This article last reviewed: 8 September 1989

TOPIC ---

What is the latest revision of the Apple EtherTalk adapter? Is there a
specific revision required to support the Internet Router and AppleTalk
Phase 2?

DISCUSSION ---

The latest revision of the Apple EtherTalk Card is Revision "K".

To be assured of good performance when there is a lot of network traffic,
you should use Apple's EtherTalk Card with EtherTalk 2.0. You should use
Revision "J" of the EtherTalk Card. Revision "J" fixed a problem in
earlier revisions that caused data corruption.

When a Macintosh IIcx is used as an EtherTalk 2.0 workstation, then Revision
"K" of the EtherTalk Card should be used. Revision "K" fixed a problem that
caused a Macintosh IIcx with only one card installed not to start.

Both problems occur only in rare instances, but to be safe, Revision "J" or "K"
should be used.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:4402