Tech Info Library

Macintosh LC II: LC Ethernet Card Requires New Driver

```
Revised:        3/19/92
Security:       Everyone
```

Macintosh LC II: LC Ethernet Card Requires New Driver

===

```
Article Created: 23 March 1992
Article Last Reviewed:
Article Last Updated:
```

TOPIC ---

I heard that the Macintosh LC Ethernet card works in the Macintosh LC II,
but requires a driver upgrade.

DISCUSSION ---

For use in the Macintosh LC II, the Ethernet card requires a ROM upgrade
that contains a new driver.

Copyright 1992, Apple Computer, Inc.

Tech Info Library Article Number:9944