Tech Info Library

Macintosh System Update 2.0.1: Description (10/93)

```
Revised:        10/1/93
Security:       Everyone
```

Macintosh System Update 2.0.1: Description (10/93)

===

Article Created: 4 October 1993

TOPIC ---

System Update 2.0.1 contains enhancements to Macintosh System 7.1 and
System 7 Pro and a collection of bug fixes. This update requires
Macintosh System Software version 7.1 or System 7 Pro.

DISCUSSION --

Macintosh System Update 2.0.1 incorporates enhancements from the two
previous versions of the Hardware System Update, versions 1.0 and 2.0.
The primary additional enhancements that Macintosh System Update 2.0.1
provides are:

• Apple HD SC Setup version 7.2.2, which gives you more flexibility to
  format large Apple hard disks between 1 and 2 gigabytes.

• AutoRemounter 1.2, which significantly reduces network traffic.

• Apple Disk First Aid 7.2, a utility that repairs damaged disks,
  which provides a new user interface.

• More efficient management of the way fonts use memory.

• Macintosh PowerBook Control Panel version 7.1.3 and Express Modem
  software version 1.1.2, which include support for communications
  software that doesn't use the Apple Communications Toolbox.

• System Enabler 131 (version 1.0.3) for the PowerBook 160, 165, 165c,
  and 180 to support 12-inch monitors and improve reliability.

• Support for System 7.1.1.

The Apple Macintosh System Update will be licensed to customers free
of charge through various on-line services, including AppleLink,

America Online, and CompuServe. The System Update 2.0.1 extension
will also be included in System 7 Pro, and will be placed directly
onto hard drives of shipping CPUs.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:13366