Tech Info Library

Power Macintosh and MacX (11/95)

```
Revised:        11/9/95
Security:       Everyone


Power Macintosh and MacX (11/95)


=====================================================================

Article Created: 28 March 1994
Article Reviewed/Updated: 9 November 1995


TOPIC -------------------------------------------------------

I'm trying to run MacX on a Power Macintosh 8100/80AV, and I'm not having any
success.  Is there a known problem with running MacX on a Power Macintosh?  I'm
running MacX version 1.2, is there a newer version I should use?  I get an error
saying something about the Comm tolls not loading properly.


DISCUSSION --------------------------------------------------

In order for Power Macintosh to properly work with MacX 1.2, you have to use
MacTCP 2.0.4 or later.  We have verified that MacTCP CDEV (1.1.1) which
originally came with MacX 1.2 does not work on Power Macintosh.  However the
MacTCP Tool 1.2 which came with MacX 1.2 is still valid to use. Also the latest
version of MacX is MacX 1.5.

MacTCP can be purchased off the Retail Price List as part number:
M8113Z/A - TCP/IP Connection for Macintosh


Article Change History:
09 Nov 1995 - Added latest version of MacX.
08 Jul 1994 - Added part number for the TCP connection product.


Support Information Services


Copyright 1994-95, Apple Computer, Inc.


Tech Info Library Article Number:15020
```