Tech Info Library

Apple IIe Card: Can't Use Comm slot device With Card (9/96)

```
Revised:        9/17/96
Security:       Everyone
```

Apple IIe Card: Can't Use Comm slot device With Card (9/96)

===

Article Created: 6 April 1994
Article Reviewed/Updated: 17 September 1996

TOPIC ---

Does the Apple IIe Card work with Macintosh computers that have a Comm Slot,
such as the Macintosh LC 575?

DISCUSSION --

The Apple IIe Card does not work in multiple card environments. Because of this,
the Apple IIe Card will not work when there is any device in the comm slot on
the Macintosh LC 575.

This article was published in the 17 September 1996 issue of the Information
Alley.

Article Change History:
17 Sep 1996 - Retitled, and rewrote discussion.

Copyright 1994-96, Apple Computer, Inc

Tech Info Library Article Number:15065