Tech Info Library

LaserWriter Pro 810: New atprint Allows Printing From AUX (5/94)

```
Revised:        5/20/94
Security:       Everyone
```

LaserWriter Pro 810: New atprint Allows Printing From AUX (5/94)

==

Article Created: 19 May 1994

TOPIC ---

When I am using A/UX 3.1 and a LaserWriter Pro 810. When I try using the "atprint" command, I get an "idle status" returned from the printer.

DISCUSSION ---

The "atprint" uses the Printer Access Protocol (PAP) to send data to the LaserWriter Pro 810. There is a new version of the "atprint" that fixes a problem in PAP that prevented A/UX from making a connection to the LaserWriter Pro 810 with A/UX 3.0.[12] or 3.1.

To locate Apple software updates, search the Tech Info Library for the article "Where To Find Apple Software Updates".

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:15387