Tech Info Library

PB 500 Series: Global Village Mercury 2.5 Software Change (2/95)

```
Revised:        2/16/95
Security:       Everyone
```

PB 500 Series: Global Village Mercury 2.5 Software Change (2/95)

===

Article Created: 16 February 1995

TOPIC ---

I just installed the new Global Village Modem software 2.5 into my Powerbook 500
series and the Compatible/Normal settings in the Powerbook Setup control panel
are gone. Is this no longer and option?

DISCUSSION --

Global Village has moved these settings into the Powerport 500 control panel. It
now has the same feel as the Apple Express Modem 1.5.5 software in this
respect.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:17210