Tech Info Library

Pwr Mac DOS Compatibility Card: Not For 68040 Computers (2/95)

```
Revised:        5/24/95
Security:       Everyone
```

Pwr Mac DOS Compatibility Card: Not For 68040 Computers (2/95)

===

Article Created: 28 February 1995

TOPIC ---

When using the DOS Compatibility Card for Macintosh (M3581LL/A) in a Quadra series computer with System 7.5 and PowerTalk, the machine freezes at startup.

DISCUSSION ---

The DOS Compatibility Card for Power Macintosh 6100/60, 6100/66, or Performa 6100 series (M3581LL/A), was not tested on 68040-based Macintosh computers. Therefore, putting this card in a Macintosh Quadra is not a supported configuration. You should not use this card for non-Power Macintosh computers.

Your configuration may work as expected if "Auto-start PC" is not selected in the PC Setup control panel. However, Apple cannot guarantee that you will not experience problems with this unsupported configuation.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:17286