Tech Info Library

Power Macintosh 9500: CD 2.0 Contents (4/97)

```
Revised:        4/29/97
Security:       Everyone


Power Macintosh 9500: CD 2.0 Contents (4/97)


=====================================================================

Article Created: 14 September 1995
Article Reviewed/Updated: 29 April 1997


TOPIC -------------------------------------------------------------

From August 8 to November 15, 1995, customers who purchased either a Power
Macintosh 9500/120 or a 9500/132 and received CD Version 1.0 are eligible to
contact the Apple Order Center to order the most recent version of the Power
Macintosh 9500 CD—CD Version 2.0.


DISCUSSION --------------------------------------------------------

The new CD offers over two dozen new and updated files (see chart, below) and
provides fixes to some known problems. Among other things, the CD provides
owners of the Power Macintosh 9500 with software they can use with the GeoPort
Telecom Adapter: Apple Telecom 2.1 and Megaphone 1.0.2. It also provides drivers
for the LaserWriter 300 and StyleWriter1200. Of particular interest to customers
on networks, the new CD provides Open Transport (OT) 1.0.6, a new version of
Open Transport that will fix a number of problems reported with OT 1.0, the
version that shipped on the original CD.

The following chart offers a comparison between the software included on the CD
initially distributed with the Power Macintosh 9500 and the CD available at the
Apple Order Center:

Begin_Table
```

COMPONENT	CD 1.0	CD 2.0	COMMENTS
System software components			
Finder	7.5.2	7.5.3	New version.
System Enabler 701	1.0	1.1	New version offers improved PCI card compatibility.
AppleCD Audio Player	2.0	2.1	New version.
Apple Menu Options	1.0.1	1.0.2	New version.

Extensions Manager	3.0	3.0.2	New version.
Memory	7.5.3	7.5.4	New version.
Monitors	7.5.2	7.5.3	New version.
Mouse	7.3	7.3.1	New version.
PC Exchange	2.0.4	2.0.5	New version.
EM Extension	3.0	3.0.2	New version.
Open Transport	1.0	1.0.6	New version offers improved stability & compatibility.
Apple CD-ROM	5.0.4	5.1.1	New version.
Apple Guide	1.2.5	1.2.7	New version.
9500 Guide Additions	n/a	1.0	Replaces 9500 Guide Additions on 9500.
EtherNet (Built-In)	1.0	1.0.1	New version.
Serial (Built-In)	1.0	1.0.2	New version.
StyleWriter I/II	2.0	n/a	SW 1200 2.1 supports SWI/II
Color SW 2400	1.6.1	2.1	New version.
LaserWriter 300	n/a	1.2	Added to 9500.
StyleWriter 1200	n/a	2.1	Added to 9500.

Extras, utilities, read me

PM9500 ReadMe	n/a	new	Replaces 9500 ReadMe on 9500.
Drive Setup	1.0	1.0.2	New version.
Apple Telecom 2.1	n/a	2.1	Added to 9500.
Megaphone	n/a	1.0.2	Added to 9500.

Unique to PM9500

Graphics Accelerator	1.0	1.0	For ATI card shipping with 9500/120.

End_Table

Customers will receive the following items with their order:

• Power Macintosh CD v2.0
• Software License Agreement

The Tech Info Library article titled "Locating Vendor Information" can help you search for the Apple Order Center's phone number.

Article Change History:
28 Apr 1997 - Removed out dated on line references.
27 May 1996 - Updated for technical accuracy.

Copyright 1995-97, Apple Computer, Inc.

Tech Info Library Article Number:18586