Tech Info Library

Power Macintosh 5200: Monitor Adjustment Cable Pinouts (10/95)

```
Revised:        10/17/95
Security:       Everyone


Power Macintosh 5200: Monitor Adjustment Cable Pinouts (10/95)


=====================================================================


Article Created: 16 October 1995


TOPIC -------------------------------------------------------------


I need the pinout of the Power Macintosh 5200 Monitor Adjustment cable, part
number 922-1513, to view the on-screen video adjustment controls.


DISCUSSION --------------------------------------------------------


In order to view the on-screen video adjustment controls, which appears after
the display test patterns, it is imperative to properly install the monitor
adjustment cable as instructed in the Service Source CD. Be sure to connect pin
1 of the Monitor Adjustment Cable 2-pin connector to pin 1 of P805 (square
marking on the analog board). The monitor adjustment cable service part number
is 922-1513.


If the monitor adjustment cable is not properly connected, then you may never
see MacTest Pro's on-screen video adjustment controls as shown in the Service
Source CD.


For your information, the following are the monitor adjustment cable pin
assignments (as seen from the cable connector):


Monitor Adjustment Cable serial end:
(Mini-Din Connector, 519-0322)


Begin_Graphic


    •   •   •
    6   7   8


    •   •       •      <------ Pins 3 and 5 are shorted together and
    3   4       5              connected to the 2-pin connector pin 1


      •   •
      1   2
```

```
2-pin Connector,
Apple p/n 517-0041:


     •  •         <------ Pin 1 must be connected to the Mini-Din
     1  2                connector, pins 3 and 5


End_Graphic
```

Support Information Services

Tech Info Library Article Number:18752