Tech Info Library

PowerBook 2300: Memory Test Error Message at Startup (5/96)

```
Revised:        5/13/96
Security:       Everyone
```

PowerBook 2300: Memory Test Error Message at Startup (5/96)

===

Article Created: 9 April 1996
Article Reviewed/Updated: 9 May 1996

TOPIC ---

I am getting a strange error message on my PowerBook 2300 computer at startup.
It says, "The built-in memory test has detected a problem. Please contact a
service technician for assistance." What does this mean?

DISCUSSION --

Issue

This problem is the result of an out-of-spec RAM card. The failure was first
noticed with some third party 12 MB RAM cards at Apple's manufacturing facility
in Cork, Ireland. A resistor change to that third party card corrected the
problem.

Resolution

You should have the RAM card replaced by the manufacturer.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19772