# Tech Info Library

## PC Compatibility Card: PostScript Errors From Windows 95 (5/96)

```
Revised:        5/20/96
Security:       Everyone
```

PC Compatibility Card: PostScript Errors From Windows 95 (5/96)

=======================================================================

Article Created: 20 May 1996

TOPIC -----------------------------------------------------------

I have a Power Macintosh and I am running Windows 95 on my DOS Compatibility
Card. When I try to print from Windows 95 to my LaserWriter printer, I get a
PostScript error from Mac OS Print Monitor.

DISCUSSION ------------------------------------------------------

A PostScript error may occur if you print more than one document at a time on
the Windows environment. When printing a second job, make sure Windows has
already finished sending the first print job.

Also, some of the settings for the Windows 95 printer driver need to be changed
from their defaults. Here are the steps to configure your Windows 95 printer
driver properly:

Step 1
------
Open the printer icon for your printer

Step 2
------
Choose Properties from the File menu

Step 3
------
Select the tab labeled Details

Step 4
------
Click Spool Settings

Step 5
------

Click "Disable bi-directional support for this printer"

Step 6
------
Click OK

Step 7
------
Click Port Settings

Step 8
------
Make sure the box labeled "Check port state before printing" is unchecked

Step 9
------
Click OK

Step 10
-------
Select the tab labeled PostScript

Step 11
-------
Click Advanced

Step 12
-------
Make sure the boxes labeled "Send CTRL+D before Job" and "Send CTRL+D after Job"
are unchecked

Step 13
-------
Click OK

Step 14
-------
Close the Properties window.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19824