Tech Info Library

7.5.3 and WGS95 PDS card (5/96)

Revised: 5/31/96
Security: Everyone

7.5.3 and WGS95 PDS card (5/96)

==========

Article Created: 31 May 1996

TOPIC ----------

A customer is trying to install system 7.5.3 on an Apple Workgroup Server 95. System 7.5 seems to install without problem but after installing the update 2.0, it hangs during the initial boot sequence.

DISCUSSION ----------

This appears to be caused by the presence of the PDS card. The Apple PDS card included with the AWS 95 is only intended to be used with the Apple Workgroup Server 95 and Under the A/UX operating system shipped with it.
This card was never tested under any other system software and none of the available versions of the Macintosh System software available now or in the future include drivers to support this card.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19901