



Tech Info Library

Problem using Apple II parallel cable with UPIC

Revised: 11/30/84
Security: Everyone

Problem using Apple II parallel cable with UPIC

=====

You may have problems using Pascal III with the Apple II Parallel Printer Interface cable, since Pascal requires different error handshaking than the cable is able to support. Rewire the cable to the pin specifications on page 16 of the Universal Parallel Interface Card manual.

Apple Tech Notes

Tech Info Library Article Number:621