



Tech Info Library

Apple IIGS Lithium Battery

Revised: 1/17/92
Security: Everyone

Apple IIGS Lithium Battery

=====

Article Created: 31 Juy 1987
Article Last Reviewed:17 July 1992
Article Last Updated:

BEFORE YOU START: Familiarize yourself with the Apple IIGS
Technical Procedures.

PROBLEM DESCRIPTION: The lithium battery is leaking and has
contaminated the logic board of the Apple IIGS.

CURE: Do NOT attempt to clean the board. Do NOT install a new
battery. The entire board, with leaking battery, should be
returned to Apple and an exchange module installed in the
customers computer. The logic board should be returned in the
standard anti-static bags and the normal shipping box.

Copyright 1987, Apple Computer, Inc.

Tech Info Library Article Number:2266