



Tech Info Library

Apple Personal Modem: Correction to User's Manual

Revised: 8/3/89
Security: Everyone

Apple Personal Modem: Correction to User's Manual

=====

This article last reviewed: 30 March 1988

In the Apple Personal Modem User's Manual (P/N 030-2001-C), page 84, Figure F-1, the picture and pin numbering of the 8-pin connector are incorrect. The APM port should be numbered from right to left, starting with the two-pin row at the bottom. The APM connector should (generally) look like this:

"Female" mini din-8	8	7	6
connector	5	4	3
	2	1	

Here's the diagram for the cable plugs:

"Male" mini din-8	6	7	8
connector	3	4	5
	1	2	

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:2807