



Tech Info Library

ImageWriter LQ: Correction to Owner's Guide

Revised: 5/3/88
Security: Everyone

ImageWriter LQ: Correction to Owner's Guide

=====

This article last reviewed: 30 March 1988

In the ImageWriter LQ Owner's Guide (P/N 030-3068-A), page 190, Figure C-1 should have pin 4 closer to pin 3:

| | | | |
|---------------------|---|---|---|
| "Female" mini din-8 | 8 | 7 | 6 |
| connector | 5 | 4 | 3 |
| | 2 | 1 | |

The numbering is correct for the port on the ImageWriter LQ.

Tech Info Library Article Number:2808