



Tech Info Library

AppleLine: Version 3.35 ROMs Correct Missing 25th Line

Revised: 6/2/88
Security: Everyone

AppleLine: Version 3.35 ROMs Correct Missing 25th Line

=====

This article last reviewed: 2 June 1988

Some AppleLine users have reported that, in MacTerminal, they can't access the 25th line on the mainframe screen.

The recent ROM revision (version 3.35), which added 3174 support to the AppleLine, is supposed to automatically bring the AppleLine up in the mode that displays the 25th line. The old ROMs did not do this: before this upgrade, the terminal type had to be set to MacTerminal in the AppleLine Supervisor to display the 25th line.

When AppleLines display the 25th line, either:

- they have the newer ROMs, or
- the AppleLine Supervisor has been set up to display it.

In either case, all AppleLines should have the newest ROMs installed to ensure compatibility with other possible configurations.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:2985