



Tech Info Library

Macintosh II Family: Fan Regulator Voids Warranty

Revised: 7/2/92
Security: Everyone

Macintosh II Family: Fan Regulator Voids Warranty

=====
Article Created: 7 October 1989
Article Last Reviewed: 25 June 1992
Article Last Updated:

TOPIC -----

I have heard of a small device that can be installed inside the Macintosh II power supply, with a remote temperature sensor mounted near the hard drive. The function of this device is to regulate fan speed based on internal temperature so that fan noise would be greatly decreased.

Does installation of such a device void Apple's warranty?

DISCUSSION -----

Installing such a device definitely voids the warranty.

We strongly discourage installing such a device because of, among other reasons, the differences in temperature within the housing versus where the device's temperature pickup is located. This would be compounded by the quantity and locations of NuBus cards, RAM, and whether there is a hard disk drive or multiple floppy drives installed.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:4648