

## Macintosh: Converter Is Necessary for V.35 Support

Revised: 6/18/92 Security: Everyone

Macintosh: Converter Is Necessary for V.35 Support

\_\_\_\_\_\_

Article Created: 23 January 1990 Article Last Reviewed: 18 June 1992

Article Last Updated:

TOPIC -----

How should a Macintosh DIN-8 port be connected for V.35 cabling specifications? The clocking for the signal will be from an external device like a DSU.

DISCUSSION -----

Although the built-in serial ports cannot directly support V.35 (due to the multiple timing/clocking elements the port must support), third-party converters are available to convert RS-232 or RS-422 to and from V.35. Such converters are available from Black Box and others. Additionally, depending on the application or functionality desired, the Serial NuBus card also supports V.35.

To locate a vendor's address and phone numbers, use the vendor name as a search string

Copyright 1990 Apple Computer, Inc.

Tech Info Library Article Number: 5065