

LW IINTX ROM Upgrade: Wrong Font Utility Shipped

Revised: 10/29/90 Security: Everyone

LW IINTX ROM Upgrade: Wrong Font Utility Shipped

This article last reviewed: 9 October 1990

TOPIC -----

My LaserWriter IINTX ROM Upgrade Kits has version 1.0 of the LaserWriter Font Utility. Shouldn't I have gotten version 2.0?

DISCUSSION -----

Many of the LaserWriter IINTX ROM Upgrade Kits have been shipped with version 1.0 of the LaserWriter Font Utility. They should have included version 2.0. This is a known problem in the build process. Currently shipping units should have version 2.0. However, if you received the wrong version, version 2.0 is available on AppleLink in the Apple Software Updates board. Use this path:

Apple Software Updates Macintosh Peripheral System Software Apple LaserWriters Personal LaserWriter NT Installation Disk Other

Copyright 1990 Apple Computer, Inc.

Tech Info Library Article Number:6196