

Tech Info Library

System 6.0.7: Installing Comm Toolbox

Revised: 6/21/91 Security: Everyone

System 6.0.7: Installing Comm Toolbox

Article Created: 16 April 1991

Article Last Reviewed: Article Last Updated:

TOPIC -----

I want to install MacTerminal 3.0 on a Macintosh LC. Unfortunately, MacTerminal 3.0 has to have certain Comm Toolbox resources into the System file. This means I have to restart from the original Installer disk, which happens to be System 6.0.5, a System that doesn't work on Macintosh LC.

I've tried to upgrade the installer disk to System 6.0.7. When I start the Macintosh LC and try to execute the installer script, the computer asks for the "Communications 1" disk. All I can find is a disk called "Communications", not "Communications 1".

DISCUSSION -----

The Communications Toolbox installation diskette that ships with MacTerminal is named "Communications". An essentially identical diskette shipped with the Macintosh Communications Toolbox package is named "Communications 1."

The Communications Toolbox 1.0 Installer Script on both diskettes (and the 6.0.7 Network Product Installer) asks you to insert the diskette "Communications 1", but you may use either diskette. Updating the CTB Installation diskette to version 6.0.7 has no effect on the resources and their locations called for by the installation script.

There isn't enough room on the CTB installation disk to conveniently update it to System 6.0.7 using the script "minimal software for any Macintosh". Many people choose to install minimal software for a specific Macintosh. An alternative is to not update the CTB installation diskette to System 6.0.7 but instead start the Macintosh with another diskette containing System Software 6.0.7. Then insert the CTB installation diskette

..TIL07148-System_6-0-7-Installing_Comm_Toolbox_(TA45560).pdf

and run the installer.

Another possibility is to get the 6.0.7 Network Products Installer off AppleLink. Use the BB Pathfinder and search on "Software and 6.0.7".

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:7148