



# Tech Info Library

## Print Shop 1.1: Fixes 1MB Apple IIGS Incompatibility

Revised: 6/21/91  
Security: Everyone

Print Shop 1.1: Fixes 1MB Apple IIGS Incompatibility

=====

Article Created: 5 March 1991  
Article Last Reviewed:  
Article Last Updated:

TOPIC -----

I'm using Broderbund's "Print Shop" on an Apple IIGS with 1MB built into the motherboard. When starting the program, I see a line of hex codes on the screen, then loading stops. The same disks work fine with the versions of Apple IIGS with 256K RAM on the motherboard and a 512K memory expansion card in the slot.

DISCUSSION -----

Broderbund has released version 1.1 of their Print Shop software that is compatible with version 3.0 of the Apple IIGS ROMs. Customers should contact Broderbund's customer service group for upgrade information.

For more information, search on "Broderbund"

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:7161