



Tech Info Library

Macintosh IIfx and 800K Drives

Revised: 7/15/92
Security: Everyone

Macintosh IIfx and 800K Drives

=====
Article Created: 26 March 1991
Article Last Reviewed: 14 July 1992
Article Last Updated:

TOPIC -----

Is it true that the Macintosh IIfx logic board does not recognize the 800K floppy drive?

DISCUSSION -----

The Macintosh IIfx recognizes both the 800K floppy drive and the SuperDrive. The logic board contains a SWIM chip, as opposed to an IWM, which recognizes and uses both drives. Our lab has a IIfx with both an 800K drive and a SuperDrive installed, and we have no problems using both drives.

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:7624