



Tech Info Library

Macintosh SE/30: 68030 Chip is Soldered to the Logic Board

Revised: 9/19/91
Security: Everyone

Macintosh SE/30: 68030 Chip is Soldered to the Logic Board

=====
Article Created: 14 June 1991
Article Last Reviewed:
Article Last Updated:

TOPIC -----

How is the Macintosh SE/30's processor chip attached to the logic board?

DISCUSSION -----

Early in the Macintosh SE/30's development, the chip was socketed. As a cost reduction enhancement, the 68030 processor chip is soldered onto the Macintosh SE/30's logic board.

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:8509