



# Tech Info Library

## Macintosh IIsi: NuBus Card Shouldn't Touch Internal Hard Drive

Revised: 7/17/92  
Security: Everyone

Macintosh IIsi: NuBus Card Shouldn't Touch Internal Hard Drive

=====  
Article Created: 14 June 1991  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

### TOPIC -----

In a Macintosh IIsi, the adapter board makes a 90 degree turn so a NuBus card can be parallel to the motherboard. Is a NuBus card supposed to actually touch the internal hard drive?

### DISCUSSION -----

The NuBus card rests just above the hard drive. There is about 1/2-inch clearance between the drive and the NuBus card depending on the card type. The card doesn't rest on the hard drive.

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:8510