



Tech Info Library

Apple IIe to Epson LX-86: Cable Recommendations

Revised: 9/11/91
Security: Everyone

Apple IIe to Epson LX-86: Cable Recommendations

=====
Article Created: 25 June 1991
Article Last Reviewed:
Article Last Updated:

TOPIC -----

We are having trouble connecting an Apple IIe configured with an Apple Parallel card to an Epson LX-86. Both the printer and Apple IIe test work okay separately. The only questionable item seems to be the cable.

DISCUSSION -----

We couldn't find anything on connecting the Epson LX-86 printer to an Apple IIe. However, there is an article in the Tech Info Library that may help: "Epson FX 80: Connecting it to an Apple II Plus or Apple IIe".

We recommend that you contact Epson to verify that the connection is the same. If the pinouts on the LX are different from the FX, get the pinouts of the LX from Epson. You can find the pinouts of the Parallel card in the "Peripheral Interface Guide" on page 2.4 with the DIP switch settings for the Parallel card on that page.

To find the article, search the Tech Info Library under "Epson" and "FX 80".

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:8515