



Tech Info Library

Macintosh Quadra 700: Support Issues

Revised: 8/6/92
Security: Everyone

Macintosh Quadra 700: Support Issues

=====
Article Created: 21 October 1991
Article Last Reviewed: 5 August 1992
Article Last Updated:

TOPIC -----

This article discusses some of the Quadra 700 support issues.

DISCUSSION -----

Processor Cooling

The Quadra 700 is designed with special cooling considerations for the 68040. For the processor to cool properly, the case must be closed whenever the Quadra 700 is running.

VRAM Bank Order

The VRAM banks must be populated in order. If there is a VRAM upgrade, the SIMM slots should be populated from the back of the CPU to the front.

SIMM Slots

The placement of the SIMM slots under the hard drive makes it unlikely that vendors will be able to develop 16MB SIMMs to work on this computer.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:8986