

PowerBook 100: When It Won't Recognize Third-Party Drive (8/92)

Are you using one terminator in the chain? This means either an external terminator or a built-in terminator to the third-party device.

The termination on the PowerBook 100 hard disk drive isn't strong enough to support the bus. So if the third-party device doesn't have an internal terminator, you need to provide an external terminator.

Support Information Services

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:9298